

Work Order ID 57273

Tuesday, April 06, 2010 9:58:11 AM

Page 1

Item ID: D3299-1

Accept

Setup Start

Revision ID:

Stop

Item Name: Fitting

Start Date: 3/31/2010 Start Qty: 1.00

Cust Item ID:

Required Date: 3/31/2010 Req'd Qty: 1.00

Customer:

Reference: Return 2010 / RA110021

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

QC: _____ Date: 10/04/06 SPC (Y/N): _____ Date: _____

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3299	C

100 QC5- Inspect part completeness to step on W/O 0.00



QC Memo 0.00

Quality Control Original B42170

110 Identify as per dwg & Stock Location: 050 0.00

Packaging Memo 0.00

Packaging Return to stock & identify with the new batch #

120 QC21- Final Inspection - Work Order Release 0.00



QC Memo 0.00

Quality Control

10/04/12

ME
10-4-9